

# General Environmental Incident Summary

**Incident:** 3648      **Date/Time Notice:** 2/10/2015      01600      **DEM Incident No:**  
**Responsible Party:** baken generator  
**Date Incident:** 2/10/2015      **Time Incident:** 0700      **Duration:** 36 hours  
**County:** Williams      **Twp:** 155      **Rng:** 100      **Sec:** 22      **Qtr:** SE SE  
**Lat:** 48.22944      **Long:** -103.51920      **Method:** Calculated  
**Location Description:** Springbrook Gas Plant, 5621 131st ave nw williston nd 58801

**Submitted By:** jonathan hippe      **Affiliation:**  
**Address:** 5621 131st ave nw  
**City:** williston      **State:** ND      **Zip:** 58801

## Received By:

### Contact Person:

50th st. west  
williston, ND 58801

**Distance Nearest Occupied Building:** 1.5 Miles      **Release Contained:** Yes

**Type of Incident:** diesel spill

**Description of Released Contaminant:** diesel

**Volume Spilled:** 50.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

### Cause of Incident:

hose fitting came undone

### Risk Evaluation:

0

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

### Potential Environmental Impacts:

none

### Action Taken or Planned:

replaced equipment to stop leak.

**Wastes Disposal Location:** cleanup be handled by clean harbor environmental services

**Agencies Involved:** NDDDES

## **Updates**

---

**Date:** 2/11/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the incident summary, this spill impacted areas at a location that doesn't fall under NDIC jurisdiction. Followup is necessary.

---

**Date:** 5/12/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

5/12/2015 at 10:26, on location. Met with facility personnel. Spill occurred in NW corner of facility along outside wall of a building. No remaining staining visible at location.